



Vehicle Condition Report

Date of Review: 09-19-16 Year: 2001
Department: PARK DEPT Make/Model: CHEV PICK UP 1500
Vehicle Number: 11 Mileage/Hours: 75274 MILES 4537 HRS

Inspection Description	Problem Area	Record Condition - Repairs Needed	Repair Cost Estimate
Vehicle Exterior			
Body Condition	Yes <input checked="" type="radio"/> No <input type="radio"/>	Rusty & very rusty under truck dings & dents ???????	
Doors	Yes <input checked="" type="radio"/> No <input type="radio"/>	Rusty & door hinges need bushings	182
Electrical	Yes <input type="radio"/> No <input checked="" type="radio"/>		
Battery - Load Test	Yes <input type="radio"/> No <input checked="" type="radio"/>		
Charging System Test	Yes <input type="radio"/> No <input checked="" type="radio"/>		
Starter Test	Yes <input type="radio"/> No <input checked="" type="radio"/>		
Vehicle Interior			
Seats	Yes <input checked="" type="radio"/> No <input type="radio"/>	Normal wear	
Windows	Yes <input type="radio"/> No <input type="radio"/>		
Door Panels	Yes <input checked="" type="radio"/> No <input type="radio"/>	Normal wear	
Floor Boards	Yes <input type="radio"/> No <input checked="" type="radio"/>		
Other	Yes <input checked="" type="radio"/> No <input type="radio"/>	Fuel lines & brake lines very rusty !!!!!!! ?????	
Other	Yes <input checked="" type="radio"/> No <input type="radio"/>	Fuel sending unit bad	475
Other	Yes <input checked="" type="radio"/> No <input type="radio"/>	Rear bumper rusted out very bad	400
Engine			
Noise	Yes <input type="radio"/> No <input checked="" type="radio"/>		
Belts	Yes <input checked="" type="radio"/> No <input type="radio"/>	Needs belt	125
Hoses	Yes <input type="radio"/> No <input checked="" type="radio"/>		
Oil Leaks	Yes <input checked="" type="radio"/> No <input type="radio"/>	Valve covers Leaking	200
Coolant System	Yes <input type="radio"/> No <input checked="" type="radio"/>		
Exhaust System	Yes <input checked="" type="radio"/> No <input type="radio"/>	Catalytic converters bad will need O2 sensors also	1,500
Other	Yes <input checked="" type="radio"/> No <input type="radio"/>	Tune up	220
Other	Yes <input type="radio"/> No <input type="radio"/>		
Other	Yes <input type="radio"/> No <input type="radio"/>		
Tires			
Left Front - Tread Depth	Yes <input type="radio"/> No <input checked="" type="radio"/>		
Left Rear - Tread Depth	Yes <input type="radio"/> No <input checked="" type="radio"/>		
Right Front - Tread Depth	Yes <input type="radio"/> No <input checked="" type="radio"/>		
Right Rear - Tread Depth	Yes <input type="radio"/> No <input checked="" type="radio"/>		



Vehicle Condition Report

Inspection Description	Problem Area	Record Condition - Repairs Needed	Repair Cost Estimate
Suspension			
Front	Yes <input type="radio"/> No <input checked="" type="radio"/>		
Rear	Yes <input type="radio"/> No <input checked="" type="radio"/>		
Shocks	Yes <input checked="" type="radio"/> No <input type="radio"/>	Rusted and leaking	450
Springs	Yes <input type="radio"/> No <input checked="" type="radio"/>		
Front End Parts	Yes <input checked="" type="radio"/> No <input type="radio"/>	Alignment	125
Transmission			
Shifting	Yes <input type="radio"/> No <input checked="" type="radio"/>		
Fluid Change	Yes <input checked="" type="radio"/> No <input type="radio"/>	Flush & filter kit	210
Leaks	Yes <input type="radio"/> No <input checked="" type="radio"/>		
Total			
Total			\$3,887.00

Other Defects/Notes

This truck is very rusty under body. Rear bumper rusted out. door hinges bad. The catalytic converters bad code po430 very costly? Fuel sending unit bad code po463. Needs tune up. Normal wear and tear on in side of truck. Valve covers leaking.

Inspector's Signature: BRAD

Date: 9-19-16

Fleet Superintendent's Recommendation:

Replace Vehicle

Repair Vehicle - Defer Replacement

Fleet Superintendent's Signature: Paul Soo

Date: 9-19-16