



Vehicle Condition Report

Date of Review: 09-19-16 Year: 2001
Department: Cemetery Make/Model: Ford F350 dump truck/plow truck
Vehicle Number: 13 Mileage/Hours: 55411

Inspection Description	Problem Area	Record Condition - Repairs Needed	Repair Cost Estimate
Vehicle Exterior			
Body Condition	Yes <input checked="" type="radio"/> No <input type="radio"/>	Some rust and dings and dents Dump box been repaired	
Doors	Yes <input checked="" type="radio"/> No <input type="radio"/>	Rust on bottoms	
Electrical	Yes <input type="radio"/> No <input checked="" type="radio"/>		
Battery - Load Test	Yes <input type="radio"/> No <input checked="" type="radio"/>		
Charging System Test	Yes <input type="radio"/> No <input checked="" type="radio"/>		
Starter Test	Yes <input type="radio"/> No <input checked="" type="radio"/>		
Vehicle Interior			
Seats	Yes <input checked="" type="radio"/> No <input type="radio"/>	Seat has hole on drivers side and been patched once	400
Windows	Yes <input type="radio"/> No <input checked="" type="radio"/>		
Door Panels	Yes <input checked="" type="radio"/> No <input type="radio"/>	Normal wear	
Floor Boards	Yes <input type="radio"/> No <input type="radio"/>		
Other	Yes <input checked="" type="radio"/> No <input type="radio"/>	Drivers side mirror broken	300
Other	Yes <input type="radio"/> No <input type="radio"/>		
Other	Yes <input type="radio"/> No <input type="radio"/>		
Engine			
Noise	Yes <input type="radio"/> No <input checked="" type="radio"/>		
Belts	Yes <input type="radio"/> No <input checked="" type="radio"/>		
Hoses	Yes <input type="radio"/> No <input checked="" type="radio"/>		
Oil Leaks	Yes <input type="radio"/> No <input checked="" type="radio"/>		
Coolant System	Yes <input checked="" type="radio"/> No <input type="radio"/>	Cooling system flush	178
Exhaust System	Yes <input checked="" type="radio"/> No <input type="radio"/>	Broken exhaust manifold bolts & leaks	800
Other	Yes <input type="radio"/> No <input type="radio"/>		
Other	Yes <input type="radio"/> No <input type="radio"/>		
Other	Yes <input type="radio"/> No <input type="radio"/>		
Tires			
Left Front - Tread Depth	Yes <input checked="" type="radio"/> No <input type="radio"/>	Will need All 6 tires in spring	1,600
Left Rear - Tread Depth	Yes <input checked="" type="radio"/> No <input type="radio"/>		
Right Front - Tread Depth	Yes <input checked="" type="radio"/> No <input type="radio"/>		
Right Rear - Tread Depth	Yes <input checked="" type="radio"/> No <input type="radio"/>		



Vehicle Condition Report

Inspection Description	Problem Area	Record Condition - Repairs Needed	Repair Cost Estimate
Suspension			
Front	Yes <input checked="" type="radio"/> No <input type="radio"/>	Sway bar links bad	125
Rear	Yes <input type="radio"/> No <input checked="" type="radio"/>		
Shocks	Yes <input checked="" type="radio"/> No <input type="radio"/>	Need replacing	450
Springs	Yes <input type="radio"/> No <input checked="" type="radio"/>		
Front End Parts	Yes <input checked="" type="radio"/> No <input type="radio"/>	Tie rod ends loose & front end alignment	420
Transmission			
Shifting	Yes <input checked="" type="radio"/> No <input type="radio"/>	shift button on lever --Dont always work	200
Fluid Change	Yes <input checked="" type="radio"/> No <input type="radio"/>	Trans flush and filter kit	265
Leaks	Yes <input type="radio"/> No <input checked="" type="radio"/>		
Total			\$4,738.00

Other Defects/Notes

This dump truck has some rust and the dump box was patched up a bought 3 years ago . Seat needs repair been patched once all ready. Drivers side mirror is broken and patched. Some Exhaust manifold bolts are broken off on engine . Sway bar links and tie rod ends bad and needs alignment. Power steering is weak when plow is on truck.

Inspector's Signature: BRAD

Date: 9-19-16

Fleet Superintendent's Recommendation:

- Replace Vehicle
- Repair Vehicle - Defer Replacement

Fleet Superintendent's Signature: Rob Spoo

Date: 9-19-16