



# Vehicle Condition Report

**Date of Review:** 01-31-2020      Year: 2006  
**Department:** CD      Make/Model: FORD TAURUS  
**Vehicle Number:** CD4      Mileage/Hours: 102563

Inspection Description	Problem Area	Record Condition - Repairs Needed	Repair Cost Estimate
<b>Vehicle Exterior</b>			
Body Condition	Yes <input checked="" type="radio"/> No <input type="radio"/>	VERY RUSTY UNDER BODY ROCKERS RUSTED OUT GONE !!!	
Doors	Yes <input checked="" type="radio"/> No <input type="radio"/>	RUSTY	
Electrical	Yes <input checked="" type="radio"/> No <input type="radio"/>	HEADLITE LENS BAD	
Battery - Load Test	Yes <input type="radio"/> No <input checked="" type="radio"/>		
Charging System Test	Yes <input type="radio"/> No <input checked="" type="radio"/>		
Starter Test	Yes <input type="radio"/> No <input checked="" type="radio"/>		
<b>Vehicle Interior</b>			
Seats	Yes <input checked="" type="radio"/> No <input type="radio"/>	SOME WEAR	
Windows	Yes <input type="radio"/> No <input checked="" type="radio"/>		
Door Panels	Yes <input type="radio"/> No <input checked="" type="radio"/>		
Floor Boards	Yes <input checked="" type="radio"/> No <input type="radio"/>	VERY RUSTY	
Other	Yes <input checked="" type="radio"/> No <input type="radio"/>	A/C has a leak ---Dose not work	
Other	Yes <input type="radio"/> No <input type="radio"/>		
Other	Yes <input type="radio"/> No <input type="radio"/>		
<b>Engine</b>			
Noise	Yes <input type="radio"/> No <input checked="" type="radio"/>		
Belts	Yes <input type="radio"/> No <input checked="" type="radio"/>		
Hoses	Yes <input checked="" type="radio"/> No <input type="radio"/>	OLD	
Oil Leaks	Yes <input checked="" type="radio"/> No <input type="radio"/>	OIL PAN & TIMING COVER LEAKS	
Coolant System	Yes <input type="radio"/> No <input checked="" type="radio"/>		
Exhaust System	Yes <input checked="" type="radio"/> No <input type="radio"/>	RUSTY	
Other	Yes <input checked="" type="radio"/> No <input type="radio"/>	POWER STEERING LINE S LEAKING	
Other	Yes <input checked="" type="radio"/> No <input type="radio"/>	BRAKE LINES VERY RUSTY !	
Other	Yes <input type="radio"/> No <input type="radio"/>		
<b>Tires</b>			
Left Front - Tread Depth	Yes <input checked="" type="radio"/> No <input type="radio"/>	NEEDS ALL 4 TIRES	
Left Rear - Tread Depth	Yes <input checked="" type="radio"/> No <input type="radio"/>		
Right Front - Tread Depth	Yes <input checked="" type="radio"/> No <input type="radio"/>		
Right Rear - Tread Depth	Yes <input checked="" type="radio"/> No <input type="radio"/>		



# Vehicle Condition Report

Inspection Description	Problem Area	Record Condition - Repairs Needed	Repair Cost Estimate
<b>Suspension</b>			
Front	Yes <input checked="" type="radio"/> No <input type="radio"/>	NEEDS ALIGNMENT	
Rear	Yes <input type="radio"/> No <input checked="" type="radio"/>		
Shocks	Yes <input checked="" type="radio"/> No <input type="radio"/>	NEED REPLACING	
Springs	Yes <input checked="" type="radio"/> No <input type="radio"/>	WEAK	
Front End Parts	Yes <input checked="" type="radio"/> No <input type="radio"/>	WORN	
<b>Transmission</b>			
Shifting	Yes <input type="radio"/> No <input checked="" type="radio"/>		
Fluid Change	Yes <input checked="" type="radio"/> No <input type="radio"/>	NEEDS FLUSH	
Leaks	Yes <input checked="" type="radio"/> No <input type="radio"/>	DIP STICK & TRANS PAN	
<b>Total</b>			
<b>Total</b>			

Other Defects/Notes
<p>CAR IS IN VERY BAD CONDITION !!!! BODY AND UNDER BODY VERY RUSTY !!! ROCKERS ARE RUSTED OUT GONE IN SPOTS !!!!!            ALL BRAKE AND FUEL LINES VERY RUSTY,HAS A SMALL BRAKE FLUID LEAK, CAR IS NOT WERTH REPAIRING</p>

Inspector's Signature: \_\_\_\_\_

Date: \_\_\_\_\_

**Fleet Superintendent's Recommendation:**

Replace Vehicle

Repair Vehicle - Defer Replacement

Fleet Superintendent's Signature: \_\_\_\_\_

Date: \_\_\_\_\_



# Vehicle Condition Report

**Date of Review:** 01-31-2020      Year: 2006  
**Department:** CD      Make/Model: FORD TAURUS  
**Vehicle Number:** CD4      Mileage/Hours: 102563

Inspection Description	Problem Area	Record Condition - Repairs Needed	Repair Cost Estimate
<b>Vehicle Exterior</b>			
Body Condition	Yes <input checked="" type="radio"/> No <input type="radio"/>	VERY RUSTY UNDER BODY ROCKERS RUSTED OUT GONE !!!	
Doors	Yes <input checked="" type="radio"/> No <input type="radio"/>	RUSTY	
Electrical	Yes <input checked="" type="radio"/> No <input type="radio"/>	HEADLITE LENS BAD	
Battery - Load Test	Yes <input type="radio"/> No <input checked="" type="radio"/>		
Charging System Test	Yes <input type="radio"/> No <input checked="" type="radio"/>		
Starter Test	Yes <input type="radio"/> No <input checked="" type="radio"/>		
<b>Vehicle Interior</b>			
Seats	Yes <input checked="" type="radio"/> No <input type="radio"/>	SOME WEAR	
Windows	Yes <input type="radio"/> No <input checked="" type="radio"/>		
Door Panels	Yes <input type="radio"/> No <input checked="" type="radio"/>		
Floor Boards	Yes <input checked="" type="radio"/> No <input type="radio"/>	VERY RUSTY	
Other	Yes <input checked="" type="radio"/> No <input type="radio"/>	A/C has a leak ---Dose not work	
Other	Yes <input type="radio"/> No <input type="radio"/>		
Other	Yes <input type="radio"/> No <input type="radio"/>		
<b>Engine</b>			
Noise	Yes <input type="radio"/> No <input checked="" type="radio"/>		
Belts	Yes <input type="radio"/> No <input checked="" type="radio"/>		
Hoses	Yes <input checked="" type="radio"/> No <input type="radio"/>	OLD	
Oil Leaks	Yes <input checked="" type="radio"/> No <input type="radio"/>	OIL PAN & TIMING COVER LEAKS	
Coolant System	Yes <input type="radio"/> No <input checked="" type="radio"/>		
Exhaust System	Yes <input checked="" type="radio"/> No <input type="radio"/>	RUSTY	
Other	Yes <input checked="" type="radio"/> No <input type="radio"/>	POWER STEERING LINE S LEAKING	
Other	Yes <input checked="" type="radio"/> No <input type="radio"/>	BRAKE LINES VERY RUSTY !	
Other	Yes <input type="radio"/> No <input type="radio"/>		
<b>Tires</b>			
Left Front - Tread Depth	Yes <input checked="" type="radio"/> No <input type="radio"/>	NEEDS ALL 4 TIRES	
Left Rear - Tread Depth	Yes <input checked="" type="radio"/> No <input type="radio"/>		
Right Front - Tread Depth	Yes <input checked="" type="radio"/> No <input type="radio"/>		
Right Rear - Tread Depth	Yes <input checked="" type="radio"/> No <input type="radio"/>		



# Vehicle Condition Report

Inspection Description	Problem Area	Record Condition - Repairs Needed	Repair Cost Estimate
<b>Suspension</b>			
Front	Yes <input checked="" type="radio"/> No <input type="radio"/>	NEEDS ALIGNMENT	
Rear	Yes <input type="radio"/> No <input checked="" type="radio"/>		
Shocks	Yes <input checked="" type="radio"/> No <input type="radio"/>	NEED REPLACING	
Springs	Yes <input checked="" type="radio"/> No <input type="radio"/>	WEAK	
Front End Parts	Yes <input checked="" type="radio"/> No <input type="radio"/>	WORN	
<b>Transmission</b>			
Shifting	Yes <input type="radio"/> No <input checked="" type="radio"/>		
Fluid Change	Yes <input checked="" type="radio"/> No <input type="radio"/>	NEEDS FLUSH	
Leaks	Yes <input checked="" type="radio"/> No <input type="radio"/>	DIP STICK & TRANS PAN	
<b>Total</b>			
<b>Total</b>			

**Other Defects/Notes**

CAR IS IN VERY BAD CONDITION !!!! BODY AND UNDER BODY VERY RUSTY !!! ROCKERS ARE RUSTED OUT GONE IN SPOTS !!!! ALL BRAKE AND FUEL LINES VERY RUSTY,HAS A SMALL BRAKE FLUID LEAK, CAR IS NOT WERTH REPAIRING

Inspector's Signature: BRAD

Date: 1-30-20

**Fleet Superintendent's Recommendation:**

Replace Vehicle

Repair Vehicle - Defer Replacement

Fleet Superintendent's Signature: [Signature]

Date: 2-5-20

DEPARTMENT CD - Community Development ID# CD4 - COMM. DEV DEPT. TAURUS RED (BRI)

JOB DATE	JOB DESCRIPTION	PARTS	COST		TOTAL	MILEAGE	HOURS
			LABOR				
2/16/2007	CHASSIS		43.50		43.50	14988	
2/16/2007	SERVICE CALL		29.00		29.00	14988	
8/30/2007	FLAT-CHANGE OR REPAIR	1.38	14.50		15.88	18907	
10/02/2007	GREASE/OIL/FILTER		29.00		29.00	19322	
8/08/2008	SERVICE CALL		29.00		29.00	25748	
4/08/2009	PM-BRAKES	6.05	17.00		23.05	30209	
4/08/2009	PM-FUEL FILTER		17.00		17.00	30209	
4/08/2009	GREASE/OIL/FILTER		17.00		17.00	30209	
4/08/2009	PM-TIRE ROTATION		17.00		17.00	30209	
9/21/2010	AIR FILTER		34.00		34.00	30209	
9/21/2010	BATTERY	22.62	6.80		29.42	35743	
9/21/2010	PM-BRAKES		17.00		17.00	35743	
9/21/2010	INSTRUMENTS		34.00		34.00	35743	
9/21/2010	PM-FUEL FILTER		34.00		34.00	35743	
9/21/2010	PM-TIRE ROTATION		34.00		34.00	35743	
1/25/2011	AIR FILTER		6.80		17.15	36866	
1/25/2011	BATTERY	10.35	17.00		17.00	36866	
1/25/2011	CHASSIS		68.00		68.00	36866	
1/25/2011	GREASE/OIL/FILTER		17.00		17.00	36866	
1/25/2011	SERVICE CALL		17.00		17.00	36866	
2/24/2011	INSTRUMENTS		34.00		34.00	36866	
4/16/2011	ELECTRICAL	28.78	6.80		35.58	37050	
4/16/2011	DIAGNOS WITH SCANNER		34.00		34.00	37492	
12/21/2011	BATTERY	106.41	68.00		68.00	37492	
12/21/2011	SERVICE CALL		68.00		174.41	39170	
7/03/2012	AIR CONDITIONING REPAIR	42.30	68.00		68.00	40687	
7/03/2012	CHASSIS		68.00		68.00	40687	
7/03/2012	PM-FUEL FILTER		34.00		34.00	40687	
7/03/2012	GREASE/OIL/FILTER		17.00		17.00	40687	
8/24/2012	NEW TIRES	677.52	68.00		745.52	41562	
3/28/2013	FLAT-CHANGE OR REPAIR	12.50	34.00		46.50	46900	
3/28/2013	PM-FUEL FILTER		34.00		34.00	46900	
3/28/2013	GREASE/OIL/FILTER		17.00		17.00	46900	
4/30/2013	CHASSIS	277.46	102.00		379.46	47824	
9/04/2013	DIAGNOS WITH SCANNER		68.00		68.00	47824	
11/01/2013	TIRE REPAIR	1.01	17.00		18.01	50650	
11/01/2013	AIR FILTER	46.12	6.80		52.92	52209	
11/01/2013	ENGINE		68.00		68.00	52209	
11/01/2013	TIRE REPAIR		17.00		17.00	52209	
11/01/2013	PM-TIRE ROTATION		17.00		17.00	52209	
11/01/2013	CHASSIS	25.46	17.00		42.46	53832	
1/21/2014	GREASE/OIL/FILTER		17.00		17.00	53832	
1/21/2014	CHASSIS		17.00		17.00	53832	
1/21/2014	PM-TIRE ROTATION		17.00		17.00	53832	
5/30/2014	ENGINE	67.84	68.00		135.84	56928	
5/30/2014	DIAGNOS WITH SCANNER		68.00		68.00	56928	
7/03/2014	BRAKE JOB-Front	161.42	34.00		297.42	57738	
7/14/2014	CHASSIS		68.00		68.00	57961	
7/24/2014	CHASSIS	7.02	6.80		13.82	58255	
8/25/2014	AIR FILTER		34.00		34.00	58255	
2/19/2015	CHASSIS		34.00		34.00	56928	

JOB DATE	JOB DESCRIPTION	PARTS	LABOR	TOTAL	MILEAGE	HOURS
12/30/2015	AIR FILTER	6.98	6.80	13.78	70523	
12/30/2015	BATTERY		17.00	17.00	70523	
12/30/2015	GREASE/OIL/FILTER		17.00	17.00	70523	
2/04/2016	CHASSIS	578.95	34.00	612.95	71410	
2/04/2016	NEW TIRES		102.00	102.00	71410	
3/29/2016	FLAT-CHANGE OR REPAIR	3.81	17.00	20.81	72778	
6/13/2016	TIRE REPAIR		102.00	102.00	74516	
7/05/2016	CHASSIS	8.68	204.00	212.68	75133	
7/08/2016	AIR FILTER	7.04	6.80	13.84	75133	
7/08/2016	GREASE/OIL/FILTER		17.00	17.00	75133	
11/08/2016	AIR FILTER	236.07	6.80	242.87	78311	
11/08/2016	BATTERY		68.00	68.00	78311	
11/08/2016	PM-BRAKES		34.00	34.00	78311	
11/08/2016	INSTRUMENTS		17.00	17.00	78311	
11/08/2016	EXHAUST		136.00	136.00	78311	
11/08/2016	PM-FUEL FILTER		34.00	34.00	78311	
11/08/2016	GREASE/OIL/FILTER		17.00	17.00	78311	
11/08/2016	PM-TIRE ROTATION		34.00	34.00	78311	
8/30/2017	INSTRUMENTS	14.38	6.80	21.18	84281	
9/11/2017	AIR FILTER	203.93	6.80	210.73	84511	
9/11/2017	BATTERY		17.00	17.00	84511	
9/11/2017	GREASE/OIL/FILTER		17.00	17.00	84511	
9/11/2017	DIAGNOS WITH SCANNER		68.00	68.00	84511	
9/11/2017	PM-TUNE UP	75.96	136.00	136.00	84511	
1/04/2018	BRAKE JOB-Front		109.50	185.46	87004	
1/04/2018	CHASSIS		73.00	73.00	87004	
1/04/2018	GREASE/OIL/FILTER		18.25	18.25	87004	
1/04/2018	TIRE REPAIR		91.25	91.25	87004	
1/04/2018	PM-TIRE ROTATION		18.25	18.25	87004	
3/27/2018	CHASSIS	52.70	73.00	125.70	89138	
3/27/2018	ENGINE		146.00	146.00	89138	
6/19/2018	ELECTRICAL		36.50	36.50	90913	
8/23/2018	INSTRUMENTS	14.98	7.30	22.28	92348	
9/17/2018	FLAT-CHANGE OR REPAIR	1.05	36.50	37.55	92921	
9/17/2018	SERVICE CALL		73.00	73.00	92921	
10/08/2018	BRAKE JOB-REAR	794.74	109.50	904.24	93308	
10/08/2018	INSTRUMENTS		73.00	73.00	93308	
10/08/2018	CHASSIS		109.50	109.50	93308	
10/08/2018	GREASE/OIL/FILTER		18.25	18.25	93308	
10/08/2018	NEW TIRES		73.00	73.00	93308	
12/28/2018	ENGINE	9.44	109.50	118.94	112270	
4/09/2019	AIR FILTER	45.46	14.60	60.06	97004	
4/09/2019	CHASSIS		219.00	219.00	97004	
4/11/2019	PM-TIRE ROTATION		18.25	18.25	97004	
4/11/2019	ENGINE	14.84	36.50	51.34	97006	
8/28/2019	AIR FILTER	15.53	14.60	30.13	99513	
8/28/2019	BATTERY		18.25	18.25	99513	
8/28/2019	EXHAUST		73.00	73.00	99513	
8/28/2019	GREASE/OIL/FILTER		18.25	18.25	99513	
11/19/2019	INSTRUMENTS	17.98	7.30	25.28	101512	

DEPARTMENT CD - Community Development

ID# CD4 - COMM. DEV DEPT. TAURUS RED (BRI

JOB DATE	JOB DESCRIPTION	PARTS	LABOR	TOTAL	MILEAGE	HOURS
1/21/2020	ELECTRICAL		73.00	73.00	102563	
TOTAL COST:		3,596.76	4,669.05	8,265.81		

  

	COST/MILE	COST/HOUR
LABOR	.04	
PARTS	.03	
TOTAL	.08	

\*\*\* END OF REPORT \*\*\*





